Approved For Release 2000/08/24: CIA-RDP71B00263R000100130025-8 14 [15] III 3349 9 3 1000 The state of the s 6 🕏 a IN 80839 25X1A6c garan terrent general german garan garan german garan garan

🕨 180723Z CITE | 8394

25X1A6c

PRIORITY INFO PRIORITY 25X1A6c

IDEALIST LOGS AVION COMMO

25X1A6c

25X1A6c 4062 (NOT SENT REF:

- SYSTEM 21, S/N 4, AND THE GROUND CHECKOUT SYSTEM S/N 2 HAVE BEEN RECEIVED AND CHECKED OUT. THE DESIGN AND WORKMANSHIP APPEARS TO BE EXCELLENT, WELL WORTH WAITING FOR.
- NO INSTRUCTION BOOK WAS RECEIVED WITH THE TEST SET, AND 2. NEITHER WAS THERE A CALIBRATION CHART TO RELATE "CODE VERSUS HOWEVER. THE FREQUENCIES OF THE RECEIVERS, I THROUGH FREQUENCY". 20, WERE WORKED OUT BY ZERO BEATING AN EXTERNAL OSCILLATOR INTO EACH RECEIVER, THEREBY MAKING IT POSSIBLE TO MAKE EFFICIENT USE OF THE TEST SET.
- THE FOUR SPARE CRYSTALS ARE MARKED GAG, GC4Y, GC5Y AND GE8. IF THESE ARE TO BE USED, IT WILL BE NECESSARY TO KNOW THE FREQUENCY SO THAT THE RECEIVERS CAN BE TUNED. ALSO, IT APPEARS THAT DUPLICATE CRYSTALS WILL BE REQUIRED TO SET UP THE GROUND PLEASE ADVISE. 0308P 1

EBBLUCES FROM AUTO Approved For Release 2000/08/24 : CIA-RDP71B00263R0004100

## Approved For Release 2000/08/24: CIA-RDP71B00263R000100130025-8

25X1A6c IN 30839 8394

PAGE 2

- 4. WHEN USING THE GROUND TEST SET, IT WAS NOTED THAT A MARKED VARIATION IN METER READINGS WERE OBTAINED WHEN THE OUTPUT OF THE RECEIVER WAS LOADED OR UNLOADED. PLEASE ADVISE:
- A. SHOULD THE RECEIVER OUTPUT TERMINALS BE LOADED OR UNLOADED WHEN TESTING A RECEIVER MODULE?
- 25X1A5a2 B. IF LOADED, WHAT IMPEDANCE?

UNABLE TO ANSWER ABOVE QUESTIONS)

- 5. IN ORDER TO COMPLETE THE BENCH TEST MOCK-UP TWO EACH OF THE FOLLOWING CONNECTORS ARE REQUESTED SOONEST:
  - A. SP-06 P-8-3S. CONTROL NUMBER 12-18-1625 APPLIES
  - B, SP-66P-22-55S.
- 6. COMPLETE MANUALS AND SCHEMATICS FOR ALL ITEMS ARE REQUESTED WHEN AVAILABLE.

CE STET TOR: 180745Z DEC 67